



*23<sup>rd</sup> April 1944: Halifax Mk BIII, LV916 EY-C*

*“Rothman C~Charlie”*

### *Information*

*The construction details for this particular aircraft have not been recorded. The date the aircraft was delivered to 78 Sqn is also not known*

*The crew were briefed to conduct a training sortie. The ATD of the aircraft from RAF Brighton, Yorkshire was not recorded*

*For reasons unknown, LV916 EY-C crashed 500 yards N of Sutton Farm, Sutton on Derwent, 7 miles SE of York at 1558*

<i>Pilot</i>	<i>E/S C.C.O. Hood +</i>
<i>Flight Engineer</i>	<i>Sgt H.B. Allan +</i>
<i>Navigator</i>	<i>E/S J. Watt +</i>
<i>Bomb Aimer</i>	<i>F/O H.R. Goddard +</i>
<i>Wireless Operator</i>	<i>Sgt L. Shaiman +</i>
<i>Mid Upper Gunner</i>	<i>Sgt B. Sheerin Inj</i>
<i>Rear Gunner</i>	<i>Sgt H.S.N. Steel +</i>

*At 18, Sgt Allan was amongst the youngest airmen killed in Bomber Command*